



**MONTHLY REPORT 20 / August 2021**  
**for**  
**COSMOPOLIS PROJECT - ROMANIA**

## ANNEX 1

### Site Photos and Notes for August 2021

Q12:




**Exterior view**



**Missing scaffold mesh,  
cleaning needed for  
safety reasons**




**Risk of accidents  
entering the building,  
scaffold with missing  
elements**




**No protection of the  
ceramic on the corridor**



**No safety balustrade –  
risk of falling**



**Electric panel to be  
protected before  
plastering on the gypsum  
board**



## Q14: completed and delivered




## Q15: Exterior view






**Exterior cleaning needed**



**Worker without safety equipment – plastering works**



**Poor quality masonry – missing adhesive on the joints (risk of cracks in the plastering layer, noise spread, loss of heating)**





**Q16: Exterior view**







**Q17 Exterior view**

